

**Flood Control Project Maintenance
Levee Inspections**

2018 Channel Summary Report

Overall Unit and Item Ratings

Tehama County Fld Control & Water Cons Dist

McClure Creek

Overall Unit Rating	Rated Item	Item Rating
M	Vegetation & Obstructions	M
	Shoaling / Sedimentation	M
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	N
	Encroachments	A

Salt Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Flood Control Project Maintenance**Unit Cover Sheet****2018 Channel Inspection Results****Tehama County Fld Control & Water Cons Dist**

Channel
McClure Creek

Channel Rating	M
Date of Inspection	6/13/2018
DWR Inspector	Bob Duffey
Accompanied By	Ryan Teubert Tehama Co. Public Works

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Tehama County Fld Control & Water Cons Dist

Channel	Channel Length	Inspection Start/End	Inspector
McClure Creek	3.50	06/13/2018 06/13/2018	Bob Duffey

Check Point / View

Truckee Avenue / Up

Rating **	A	Issue No.	1	GPS Lat/Long
Issue Type +	Ma	Location *		40.009840 °
Category	Rivers, Channels & Designated Flood			-122.200180 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0019_3_c_2012_1			
Action/Comments				
Inspector Comments: No vegetation in the channel.				

Photo 1 of 1 : CH_2018_NA0019_3_1_20180618_00008.jpg



View of the upstream extension of McClure Creek at Truckee Avenue.

Rating **	A	Issue No.	2	GPS Lat/Long
Issue Type +	Ma	Location *		40.009840 °
Category	Rivers, Channels & Designated Flood			-122.200180 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0019_3_c_2012_2			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	5	GPS Lat/Long
Issue Type +	Ma	Location *		40.009840 °
Category	Rivers, Channels & Designated Flood			-122.200180 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0019_3_c_2012_5			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel bank.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Tehama County Fld Control & Water Cons Dist

Channel	Channel Length	Inspection Start/End	Inspector
McClure Creek	3.50	06/13/2018 06/13/2018	Bob Duffey

Check Point / View

Truckee Avenue / Up (cont)

Rating **	N	Issue No.	4	GPS Lat/Long
Issue Type +	Ma	Location *		40.009840 °
Category	Rivers, Channels & Designated Flood			-122.200180 °
Item	Revetments			
DWR ID	DWR_NA0019_3_c_2012_4			

Action/Comments

Inspector Comments: No riprap along the banks of the channel.

No Photos

Rating **	A	Issue No.	3	GPS Lat/Long
Issue Type +	Ma	Location *		40.009840 °
Category	Rivers, Channels & Designated Flood			-122.200180 °
Item	Encroachments			
DWR ID	DWR_NA0019_3_c_2012_3			

Action/Comments

Inspector Comments: No encroachments in the channel.

No Photos

Check Point / View

Truckee Avenue / Down

Rating **	A	Issue No.	6	GPS Lat/Long
Issue Type +	Ma	Location *		40.009840 °
Category	Rivers, Channels & Designated Flood			-122.200180 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0019_3_c_2012_6			

Action/Comments

Inspector Comments: No vegetation in the channel.

Photo 1 of 1 : CH_2018_NA0019_3_6_20180618_00009.jpg



View of the downstream extension of McClure Creek at Truckee Avenue.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Tehama County Fld Control & Water Cons Dist

Channel	Channel Length	Inspection Start/End	Inspector
McClure Creek	3.50	06/13/2018 06/13/2018	Bob Duffey

Check Point / View				
Truckee Avenue / Down (cont)				
Rating **	A	Issue No.	7	GPS Lat/Long
Issue Type +	Ma	Location *		40.009840 °
Category	Rivers, Channels & Designated Flood			-122.200180 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0019_3_c_2012_7			
Action/Comments				
Inspector Comments: No shoaling present.				

No Photos

No Photos

Rating **	A	Issue No.	8	GPS Lat/Long
Issue Type +	Ma	Location *		40.009840 °
Category	Rivers, Channels & Designated Flood			-122.200180 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0019_3_c_2012_8			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel bank.				

No Photos

No Photos

Rating **	N	Issue No.	9	GPS Lat/Long
Issue Type +	Ma	Location *		40.009840 °
Category	Rivers, Channels & Designated Flood			-122.200180 °
Item	Revetments			
DWR ID	DWR_NA0019_3_c_2012_9			
Action/Comments				
Inspector Comments: No riprap along the banks of the channel.				

No Photos

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Tehama County Fld Control & Water Cons Dist

Channel	Channel Length	Inspection Start/End	Inspector
McClure Creek	3.50	06/13/2018 06/13/2018	Bob Duffey

Check Point / View				
Truckee Avenue / Down (cont)				
Rating **	A	Issue No.	10	GPS Lat/Long
Issue Type +	Ma	Location *		40.009840 °
Category	Rivers, Channels & Designated Flood			-122.200180 °
Item	Encroachments			
DWR ID	DWR_NA0019_3_c_2012_10			
Action/Comments				
Inspector Comments: No encroachments in the channel				

No Photos

Check Point / View				
Highway 99 W / Up				
Rating **	M	Issue No.	11	GPS Lat/Long
Issue Type +	Ma	Location *		40.007430 °
Category	Rivers, Channels & Designated Flood			-122.171780 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0019_3_c_2012_11			
Action/Comments				
Inspector Comments: Remove all vegetation from channel before winter.				

Photo 1 of 1 : CH_2018_NA0019_3_11_20180618_00010.jpg



Upstream view from Highway 99W. Note the vegetation in the channel.

Rating **	A	Issue No.	12	GPS Lat/Long
Issue Type +	Ma	Location *		40.007430 °
Category	Rivers, Channels & Designated Flood			-122.171780 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0019_3_c_2012_12			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Tehama County Fld Control & Water Cons Dist

Channel	Channel Length	Inspection Start/End	Inspector
McClure Creek	3.50	06/13/2018 06/13/2018	Bob Duffey

Check Point / View

Highway 99 W / Up (cont)

Rating **	A	Issue No.	13	GPS Lat/Long
Issue Type +	Ma	Location *		40.007430 °
Category	Rivers, Channels & Designated Flood			-122.171780 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0019_3_c _ 2012_13			
Action/Comments				
Inspector Comments: No erosion along the banks of the channel.				

No Photos

Rating **	N	Issue No.	14	GPS Lat/Long
Issue Type +	Ma	Location *		40.007430 °
Category	Rivers, Channels & Designated Flood			-122.171780 °
Item	Revetments			
DWR ID	DWR_NA0019_3_c _ 2012_14			
Action/Comments				
Inspector Comments: No riprap along the bank of the channel.				

No Photos

Rating **	A	Issue No.	15	GPS Lat/Long
Issue Type +	Ma	Location *		40.007430 °
Category	Rivers, Channels & Designated Flood			-122.171780 °
Item	Encroachments			
DWR ID	DWR_NA0019_3_c _ 2012_15			
Action/Comments				
Inspector Comments: No trash or debris in the channel.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Tehama County Fld Control & Water Cons Dist

Channel	Channel Length	Inspection Start/End	Inspector
McClure Creek	3.50	06/13/2018 06/13/2018	Bob Duffey

Check Point / View

Highway 99 W / Down

Rating **	M	Issue No.	16	GPS Lat/Long
Issue Type +	Ma	Location *		40.007430 °
Category	Rivers, Channels & Designated Flood			-122.171780 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0019_3_c_2012_16			
Action/Comments				
Inspector Comments: Remove the irrigation pipe and all vegetation from channel before winter.				

Photo 1 of 1 : CH_2018_NA0019_3_16_20180618_00011.jpg



Downstream view from Highway 99 W. There is an irrigation pipe going across the channel.

Rating **	A	Issue No.	17	GPS Lat/Long
Issue Type +	Ma	Location *		40.007430 °
Category	Rivers, Channels & Designated Flood			-122.171780 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0019_3_c_2012_17			
Action/Comments				
Inspector Comments: No shoaling present.				

No Photos

Rating **	A	Issue No.	18	GPS Lat/Long
Issue Type +	Ma	Location *		40.007430 °
Category	Rivers, Channels & Designated Flood			-122.171780 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0019_3_c_2012_18			
Action/Comments				
Inspector Comments: No erosion encroaching into the channel bank.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Tehama County Fld Control & Water Cons Dist

Channel	Channel Length	Inspection Start/End	Inspector
McClure Creek	3.50	06/13/2018 06/13/2018	Bob Duffey

Check Point / View

Highway 99 W / Down (cont)

Rating **	N	Issue No.	19	GPS Lat/Long
Issue Type +	Ma	Location *		40.007430 °
Category	Rivers, Channels & Designated Flood			-122.171780 °
Item	Revetments			
DWR ID	DWR_NA0019_3_c_2012_19			

Action/Comments

Inspector Comments: No riprap along the banks of the channel.

No Photos

Rating **	M	Issue No.	20	GPS Lat/Long
Issue Type +	En	Location *		40.007430 °
Category	Rivers, Channels & Designated Flood			-122.171780 °
Item	Encroachments			
DWR ID	DWR_NA0019_3_c_2012_20			

Action/Comments

Inspector Comments: There is an irrigation pipeline going across the channel.

No Photos

Check Point / View

Hamilton Road / Up

Rating **	M	Issue No.	41	GPS Lat/Long
Issue Type +	Ma	Location *		40.017400 °
Category	Rivers, Channels & Designated Flood			-122.146540 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0019_3_c_2012_41			

Action/Comments

Inspector Comments: Remove all vegetation from the channel before winter. Arundo should be eradicated.

Photo 1 of 1 : CH_2018_NA0019_3_41_20180618_00014.jpg



Upstream from Hamilton Road. Dense vegetation in the channel.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Tehama County Fld Control & Water Cons Dist

Channel	Channel Length	Inspection Start/End	Inspector
McClure Creek	3.50	06/13/2018 06/13/2018	Bob Duffey

Check Point / View

Hamilton Road / Up (cont)

Rating **	M	Issue No.	42	GPS Lat/Long
Issue Type +	Ma	Location *		40.017400 °
Category	Rivers, Channels & Designated Flood			-122.146540 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0019_3_c_2012_42			

Action/Comments

Inspector Comments: Remove the sediment from the channel.

No Photos

Rating **	A	Issue No.	43	GPS Lat/Long
Issue Type +	Ma	Location *		40.017400 °
Category	Rivers, Channels & Designated Flood			-122.146540 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0019_3_c_2012_43			

Action/Comments

Inspector Comments: No erosion encroaching into the channel bank.

No Photos

Rating **	N	Issue No.	44	GPS Lat/Long
Issue Type +	Ma	Location *		40.017400 °
Category	Rivers, Channels & Designated Flood			-122.146540 °
Item	Revetments			
DWR ID	DWR_NA0019_3_c_2012_44			

Action/Comments

Inspector Comments: No riprap along the banks of the channel.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Tehama County Fld Control & Water Cons Dist

Channel	Channel Length	Inspection Start/End	Inspector
McClure Creek	3.50	06/13/2018 06/13/2018	Bob Duffey

Check Point / View

Hamilton Road / Up (cont)

Rating **	M	Issue No.	45	GPS Lat/Long
Issue Type +	Ma	Location *		40.017400 °
Category	Rivers, Channels & Designated Flood			-122.146540 °
Item	Encroachments			
DWR ID	DWR_NA0019_3_c_2012_45			

Action/Comments

Inspector Comments: There is debris built-up in the vegetation.

No Photos

Check Point / View

Hamilton Road / Down

Rating **	M	Issue No.	46	GPS Lat/Long
Issue Type +	Ma	Location *		40.017400 °
Category	Rivers, Channels & Designated Flood			-122.146540 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0019_3_c_2012_46			

Action/Comments

Inspector Comments: Remove all vegetation from the channel before winter. Arundo should be eradicated.

Photo 1 of 1 : CH_2018_NA0019_3_46_20180618_00013.jpg



Downstream from Hamilton Road. Dense vegetation in the channel.

Rating **	M	Issue No.	47	GPS Lat/Long
Issue Type +	Ma	Location *		40.017400 °
Category	Rivers, Channels & Designated Flood			-122.146540 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0019_3_c_2012_47			

Action/Comments

Inspector Comments: There is sediment in the channel.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Tehama County Fld Control & Water Cons Dist

Channel	Channel Length	Inspection Start/End	Inspector
McClure Creek	3.50	06/13/2018 06/13/2018	Bob Duffey

Check Point / View

Hamilton Road / Down (cont)

Rating **	A	Issue No.	48	GPS Lat/Long
Issue Type +	Ma	Location *		40.017400 °
Category	Rivers, Channels & Designated Flood			-122.146540 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0019_3_c_2012_48			

Action/Comments

Inspector Comments: No erosion encroaching into the channel bank.

No Photos

Rating **	N	Issue No.	49	GPS Lat/Long
Issue Type +	Ma	Location *		40.017400 °
Category	Rivers, Channels & Designated Flood			-122.146540 °
Item	Revetments			
DWR ID	DWR_NA0019_3_c_2012_49			

Action/Comments

Inspector Comments: No riprap along the banks of the channel.

No Photos

Rating **	A	Issue No.	50	GPS Lat/Long
Issue Type +	Ma	Location *		40.017400 °
Category	Rivers, Channels & Designated Flood			-122.146540 °
Item	Encroachments			
DWR ID	DWR_NA0019_3_c_2012_50			

Action/Comments

Photo 1 of 1 : CH_2018_NA0019_3_50_20180618_00012.jpg



There is no significant debris in the channel.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

Flood Control Project Maintenance**Unit Cover Sheet****2018 Channel Inspection Results****Tehama County Fld Control & Water Cons Dist**

Channel
Salt Creek

Channel Rating	A
Date of Inspection	6/13/2018
DWR Inspector	Bob Duffey
Accompanied By	Ryan Teubert Tehama Co. Public Works

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Tehama County Fld Control & Water Cons Dist


Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	06/13/2018 06/13/2018	Bob Duffey

Check Point / View

Upstream Limit / Up

Rating **	A	Issue No.	1	GPS Lat/Long
Issue Type +	Ma	Location *		40.157120 °
Category	Rivers, Channels & Designated Flood			-122.164250 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0019_4_c_2012_1			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 1 : CH_2018_NA0019_4_1_20180625_00007.jpg



Upstream view of Salt Creek from the railroad car bridge.

Rating **	A	Issue No.	2	GPS Lat/Long
Issue Type +	Ma	Location *		40.157120 °
Category	Rivers, Channels & Designated Flood			-122.164250 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0019_4_c_2012_2			
Action/Comments				
Inspector Comments: No shoaling or sedimentation that would affect the capacity noted.				

No Photos

Rating **	A	Issue No.	3	GPS Lat/Long
Issue Type +	Ma	Location *		40.157120 °
Category	Rivers, Channels & Designated Flood			-122.164250 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0019_4_c_2012_3			
Action/Comments				
Inspector Comments: No erosion that would affect the capacity was noted.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Tehama County Fld Control & Water Cons Dist

Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	06/13/2018 06/13/2018	Bob Duffey

Check Point / View

Upstream Limit / Up (cont)

Rating **	A	Issue No.	4	GPS Lat/Long
Issue Type +	Ma	Location *		40.157120 °
Category	Rivers, Channels & Designated Flood			-122.164250 °
Item	Revetments			
DWR ID	DWR_NA0019_4_c_2012_4			

Action/Comments

Inspector Comments: Revetment appeared to be in good condition.

No Photos

Rating **	A	Issue No.	5	GPS Lat/Long
Issue Type +	Ma	Location *		40.157120 °
Category	Rivers, Channels & Designated Flood			-122.164250 °
Item	Encroachments			
DWR ID	DWR_NA0019_4_c_2012_5			

Action/Comments

Inspector Comments: No encroachments were observed that would affect the flow.

No Photos

Check Point / View

Upstream Limit / Down

Rating **	A	Issue No.	6	GPS Lat/Long
Issue Type +	Ma	Location *		40.157120 °
Category	Rivers, Channels & Designated Flood			-122.164250 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0019_4_c_2012_6			

Action/Comments

Inspector Comments: Minimal scattered obstructions or vegetation. The flow is not impeded.

Photo 1 of 1 : CH_2018_NA0019_4_6_20180625_00009.jpg



Downstream view of salt Creek from the railroad car bridge.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Tehama County Fld Control & Water Cons Dist

Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	06/13/2018 06/13/2018	Bob Duffey

Check Point / View

Upstream Limit / Down (cont)

Rating **	A	Issue No.	7	GPS Lat/Long
Issue Type +	Ma	Location *		40.157120 °
Category	Rivers, Channels & Designated Flood			-122.164250 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0019_4_c_2012_7			
Action/Comments				
Inspector Comments: No shoaling or sedimentation that would affect the capacity noted.				

No Photos

Rating **	A	Issue No.	8	GPS Lat/Long
Issue Type +	Ma	Location *		40.157120 °
Category	Rivers, Channels & Designated Flood			-122.164250 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0019_4_c_2012_8			
Action/Comments				
Inspector Comments: No erosion that would affect the capacity was noted.				

No Photos

Rating **	A	Issue No.	9	GPS Lat/Long
Issue Type +	Ma	Location *		40.157120 °
Category	Rivers, Channels & Designated Flood			-122.164250 °
Item	Revetments			
DWR ID	DWR_NA0019_4_c_2012_9			
Action/Comments				
Inspector Comments: Revetment appeared to be in good condition or not needed.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Tehama County Fld Control & Water Cons Dist

Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	06/13/2018 06/13/2018	Bob Duffey

Check Point / View				
Upstream Limit / Down (cont)				
Rating **	A	Issue No.	10	GPS Lat/Long
Issue Type +	Ma	Location *		40.157120 °
Category	Rivers, Channels & Designated Flood			-122.164250 °
Item	Encroachments			
DWR ID	DWR_NA0019_4_c_2012_10			
Action/Comments				
Inspector Comments: No encroachments were observed that would effect the flow.				

No Photos

Check Point / View				
Extension of Salt Creek Road / Up				
Rating **	A	Issue No.	11	GPS Lat/Long
Issue Type +	Ma	Location *		40.156770 °
Category	Rivers, Channels & Designated Flood			-122.163670 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0019_4_c_2012_11			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

No Photos

Rating **	A	Issue No.	12	GPS Lat/Long
Issue Type +	Ma	Location *		40.156770 °
Category	Rivers, Channels & Designated Flood			-122.163670 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0019_4_c_2012_12			
Action/Comments				
Inspector Comments: No shoaling or sedimentation that would affect the capacity noted.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Tehama County Fld Control & Water Cons Dist

Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	06/13/2018 06/13/2018	Bob Duffey

Check Point / View

Extension of Salt Creek Road / Up (cont)

Rating **	A	Issue No.	13	GPS Lat/Long
Issue Type +	Ma	Location *		40.156770 °
Category	Rivers, Channels & Designated Flood			-122.163670 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0019_4_c_2012_13			

Action/Comments

Inspector Comments: No erosion that would affect the capacity was noted.

No Photos

Rating **	A	Issue No.	14	GPS Lat/Long
Issue Type +	Ma	Location *		40.156770 °
Category	Rivers, Channels & Designated Flood			-122.163670 °
Item	Revetments			
DWR ID	DWR_NA0019_4_c_2012_14			

Action/Comments

Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.

Photo 1 of 1 : CH_2018_NA0019_4_14_20180625_00010.jpg



The landowner has placed rip rap along all erosion sites.

Rating **	A	Issue No.	15	GPS Lat/Long
Issue Type +	Ma	Location *		40.156770 °
Category	Rivers, Channels & Designated Flood			-122.163670 °
Item	Encroachments			
DWR ID	DWR_NA0019_4_c_2012_15			

Action/Comments

Inspector Comments: No encroachments were observed that would affect the flow.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Tehama County Fld Control & Water Cons Dist

Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	06/13/2018 06/13/2018	Bob Duffey

Check Point / View

Extension of Salt Creek Road / Down

Rating **	A	Issue No.	16	GPS Lat/Long
Issue Type +	Ma	Location *		40.156770 °
Category	Rivers, Channels & Designated Flood			-122.163670 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0019_4_c_2012_16			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impacted.

No Photos

Rating **	A	Issue No.	17	GPS Lat/Long
Issue Type +	Ma	Location *		40.156770 °
Category	Rivers, Channels & Designated Flood			-122.163670 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0019_4_c_2012_17			

Action/Comments

Inspector Comments: No shoaling or sedimentation that would affect the capacity noted.

No Photos

Rating **	A	Issue No.	18	GPS Lat/Long
Issue Type +	Ma	Location *		40.156770 °
Category	Rivers, Channels & Designated Flood			-122.163670 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0019_4_c_2012_18			

Action/Comments

Inspector Comments: No erosion that would affect the capacity was noted.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Tehama County Fld Control & Water Cons Dist

Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	06/13/2018 06/13/2018	Bob Duffey

Check Point / View

Extension of Salt Creek Road / Down (cont)

Rating **	A	Issue No.	19	GPS Lat/Long
Issue Type +	Ma	Location *		40.156770 °
Category	Rivers, Channels & Designated Flood			-122.163670 °
Item	Revetments			
DWR ID	DWR_NA0019_4_c_2012_19			

Action/Comments

Inspector Comments: Revetment appeared to be in good condition or not needed.

No Photos

Rating **	A	Issue No.	20	GPS Lat/Long
Issue Type +	Ma	Location *		40.156770 °
Category	Rivers, Channels & Designated Flood			-122.163670 °
Item	Encroachments			
DWR ID	DWR_NA0019_4_c_2012_20			

Action/Comments

Inspector Comments: No encroachments were observed that would affect the flow.

No Photos

Check Point / View

2,800' upstream of downstream limit / Up

Rating **	A	Issue No.	21	GPS Lat/Long
Issue Type +	Ma	Location *		40.151480 °
Category	Rivers, Channels & Designated Flood			-122.157590 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0019_4_c_2012_21			

Action/Comments

Photo 1 of 1 : CH_2018_NA0019_4_21_20180625_00011.jpg



Channel has been cleared of logs and vegetation by landowner.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Tehama County Fld Control & Water Cons Dist

Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	06/13/2018 06/13/2018	Bob Duffey

Check Point / View				
2,800' upstream of downstream limit / Up (cont)				
Rating **	A	Issue No.	22	GPS Lat/Long
Issue Type +	Ma	Location *		40.151480 °
Category	Rivers, Channels & Designated Flood			-122.157590 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0019_4_c_2012_22			
Action/Comments				
Inspector Comments: No shoaling or sedimentation that would affect the capacity noted.				

No Photos

Rating **	A	Issue No.	23	GPS Lat/Long
Issue Type +	Ma	Location *		40.151480 °
Category	Rivers, Channels & Designated Flood			-122.157590 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0019_4_c_2012_23			
Action/Comments				

No Photos

Rating **	A	Issue No.	24	GPS Lat/Long
Issue Type +	Ma	Location *		40.151480 °
Category	Rivers, Channels & Designated Flood			-122.157590 °
Item	Revetments			
DWR ID	DWR_NA0019_4_c_2012_24			
Action/Comments				
Inspector Comments: Revetment appeared to be in good condition.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Tehama County Fld Control & Water Cons Dist

Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	06/13/2018 06/13/2018	Bob Duffey

Check Point / View				
2,800' upstream of downstream limit / Up (cont)				
Rating **	A	Issue No.	25	GPS Lat/Long
Issue Type +	Ma	Location *		40.151480 °
Category	Rivers, Channels & Designated Flood			-122.157590 °
Item	Encroachments			
DWR ID	DWR_NA0019_4_c_2012_25			
Action/Comments				
Inspector Comments: No encroachments were observed that would affect the flow.				

No Photos

Check Point / View				
2,800' upstream of downstream limit / Down				
Rating **	A	Issue No.	26	GPS Lat/Long
Issue Type +	Ma	Location *		40.151480 °
Category	Rivers, Channels & Designated Flood			-122.157590 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0019_4_c_2012_26			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impacted.				

No Photos

Rating **	A	Issue No.	27	GPS Lat/Long
Issue Type +	Ma	Location *		40.151480 °
Category	Rivers, Channels & Designated Flood			-122.157590 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0019_4_c_2012_27			
Action/Comments				
Inspector Comments: No shoaling or sedimentation that would affect the capacity noted.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Tehama County Fld Control & Water Cons Dist

Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	06/13/2018 06/13/2018	Bob Duffey

Check Point / View

2,800' upstream of downstream limit / Down (cont)

Rating **	A	Issue No.	28	GPS Lat/Long
Issue Type +	Ma	Location *		40.151480 °
Category	Rivers, Channels & Designated Flood			-122.157590 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0019_4_c_2012_28			

Action/Comments

Inspector Comments: No erosion that would affect the capacity was noted.

No Photos

Rating **	A	Issue No.	29	GPS Lat/Long
Issue Type +	Ma	Location *		40.151480 °
Category	Rivers, Channels & Designated Flood			-122.157590 °
Item	Revetments			
DWR ID	DWR_NA0019_4_c_2012_29			

Action/Comments

Inspector Comments: Revetment appeared to be in good condition.

No Photos

Rating **	A	Issue No.	30	GPS Lat/Long
Issue Type +	Ma	Location *		40.151480 °
Category	Rivers, Channels & Designated Flood			-122.157590 °
Item	Encroachments			
DWR ID	DWR_NA0019_4_c_2012_30			

Action/Comments

Inspector Comments: No encroachments were observed that would affect the flow.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Tehama County Fld Control & Water Cons Dist

Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	06/13/2018 06/13/2018	Bob Duffey

Check Point / View

100' upstream of confluence with Sac. R. / Up

Rating **	A	Issue No.	31	GPS Lat/Long
Issue Type +	Ma	Location *		40.147230 °
Category	Rivers, Channels & Designated Flood			-122.154420 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0019_4_c _2012_31			
Action/Comments				

Photo 1 of 1 : CH_2018_NA0019_4_31_20180625_00012.jpg



Upstream view of Salt Creek from the confluence of the Sacramento River.

Rating **	A	Issue No.	32	GPS Lat/Long
Issue Type +	Ma	Location *		40.147230 °
Category	Rivers, Channels & Designated Flood			-122.154420 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0019_4_c_2012_32			
Action/Comments				
Inspector Comments: No shoaling or sedimentation that would affect the capacity noted.				

No Photos

Rating **	A	Issue No.	33	GPS Lat/Long
Issue Type +	Ma	Location *		40.147230 °
Category	Rivers, Channels & Designated Flood			-122.154420 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0019_4_c _2012_33			
Action/Comments				
Inspector Comments: No erosion that would affect the capacity was noted.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Tehama County Fld Control & Water Cons Dist

Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	06/13/2018 06/13/2018	Bob Duffey

Check Point / View

100' upstream of confluence with Sac. R. / Up (cont)

Rating **	A	Issue No.	34	GPS Lat/Long
Issue Type +	Ma	Location *		40.147230 °
Category	Rivers, Channels & Designated Flood			-122.154420 °
Item	Revetments			
DWR ID	DWR_NA0019_4_c_2012_34			

Action/Comments

Inspector Comments: Revetment appeared to be in good condition or not needed.

No Photos

Rating **	A	Issue No.	35	GPS Lat/Long
Issue Type +	Ma	Location *		40.147230 °
Category	Rivers, Channels & Designated Flood			-122.154420 °
Item	Encroachments			
DWR ID	DWR_NA0019_4_c_2012_35			

Action/Comments

Inspector Comments: No encroachments were observed that would affect the flow.

No Photos

Check Point / View

100' upstream of confluence with Sac. R. / Down

Rating **	A	Issue No.	36	GPS Lat/Long
Issue Type +	Ma	Location *		40.147230 °
Category	Rivers, Channels & Designated Flood			-122.154420 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0019_4_c_2012_36			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impacted.

Photo 1 of 1 : CH_2018_NA0019_4_36_20180625_00013.jpg



Downstream view of the confluence of the Sacramento River.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Tehama County Fld Control & Water Cons Dist

Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	06/13/2018 06/13/2018	Bob Duffey

Check Point / View

100' upstream of confluence with Sac. R. / Down (cont)

Rating **	A	Issue No.	37	GPS Lat/Long
Issue Type +	Ma	Location *		40.147230 °
Category	Rivers, Channels & Designated Flood			-122.154420 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0019_4_c _ 2012_37			
Action/Comments				
Inspector Comments: No shoaling or sedimentation that would affect the capacity noted.				

No Photos

Rating **	A	Issue No.	38	GPS Lat/Long
Issue Type +	Ma	Location *		40.147230 °
Category	Rivers, Channels & Designated Flood			-122.154420 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0019_4_c _ 2012_38			
Action/Comments				
Inspector Comments: No erosion that would affect the capacity was noted.				

No Photos

Rating **	N	Issue No.	39	GPS Lat/Long
Issue Type +	Ma	Location *		40.147230 °
Category	Rivers, Channels & Designated Flood			-122.154420 °
Item	Revetments			
DWR ID	DWR_NA0019_4_c _ 2012_39			
Action/Comments				
Inspector Comments: This item does not apply to this inspection.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2018

Tehama County Fld Control & Water Cons Dist

Channel	Channel Length	Inspection Start/End	Inspector
Salt Creek	1.60	06/13/2018 06/13/2018	Bob Duffey

Check Point / View
100' upstream of confluence with Sac. R. / Down (cont)

Rating **	A	Issue No.	40	GPS Lat/Long
Issue Type +	Ma	Location *		40.147230 °
Category	Rivers, Channels & Designated Flood			-122.154420 °
Item	Encroachments			
DWR ID	DWR_NA0019_4_c_2012_40			

No Photos

Action/Comments

Inspector Comments: No encroachments were observed that would affect the flow.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement